

Lightning Damage to St Odulphus (2)
21/22 January 2013



St Odulphus interior (1) after lightning strike (RW)



St Odulphus interior (2) after lightning strike (RW)



St Odulphus interior - large hole in roof (RW)



St Odulphus interior - beneath the large roof hole (RW)



On the tower roof (1) (RW)



On the tower roof (2) (RW)



On the tower roof (3) (RW)



On the tower roof (4) (RW)



The large roof hole from outside (TR)



The large roof hole from inside (TR)



Roof holes looking down from the tower (TR)

Contact Us

Edited: 22 Jan 2023

Photographs by Richard Warwick (RW) and Tony Rowe (TR)